

Wichtige Produktinformation...

zum Zählwerk für den AppFix Roll n' Cut und den TreeMaxxEasyReachPro

Es ist unbedingt darauf zu achten, dass der Nullstellenhebel des Zählwerks vor dem Start **zweimal vollständig** nach hinten gedrückt wird (siehe Bild 1).

Dieser Vorgang ist unter Umständen zu wiederholen, sollte das Zählwerk nicht vollständig auf Null (00000) gestellt sein (siehe Bild 2) oder nicht gleich anlaufen.

Das Zählwerk arbeitet mechanisch mit sensiblen Zahnrädern und diese müssen unbedingt vor dem Start ineinandergreifen!



Bild/Picture 1



Bild/Picture 2

Important product information...

concerning the counter of the AppFix Roll n' Cut and the TreeMaxx EasyReach Pro

It is essential to ensure, that the reset lever/handle of the counter is pushed twice fully to the rear before you start (see picture 1).

This process should be repeated in following cases:

- if the counter does not switch completely to zero (00000)
- if the counter does not start at one go (see picture 2).

The counter works mechanically with some sensitive gear wheels and before the counter should start to count, the gear wheels have to interlock.