

NanoEx

YT10YTCNE01

Signmaker's - Edition

Made in Germany



Entfernt Nano-Beschichtungen von Glas und Lack

Verarbeitungshinweis

Zur Anwendung wird weiterhin benötigt:
Polierwolle oder ein fusselfreies Tuch
z.B. unser YelloFleecePro.

- **Vorbereitung:**
Fläche mit YelloJack und / oder handels-
üblichen Reiniger gründlich reinigen.
- **NanoEx vor Gebrauch gut schütteln!**
- **Die Reinigungsmilch auf das Tuch oder
die Polierwolle geben. Auf die zu
behandelnde Fläche in kreisenden
Bewegungen auftragen, dabei nicht zu
stark drücken.**
- **Bitte unbedingt die gesamte Oberflä-
che wie Glasscheibe, Türe, Kotflügel
usw. bearbeiten!!!**
- **Anschließend die Fläche mit reichlich
Wasser abspülen und trocknen lassen.**
- **Je nach Beschichtungsgrad den
Arbeitsgang eventuell wiederholen.**

Gefahrenhinweise

H315 - Verursacht Hautreizungen.
H317 - Kann allergische Hautreaktionen verursachen.
H318 - Verursacht schwere Augenschäden.

Sicherheitshinweise

P264 - Nach Gebrauch die Hände gründlich waschen.
P280 - Schutzhandschuhe, Augenschutz tragen.
P305+P351+P338 - BEI KONTAKT MIT DEN AUGEN: Einige
Minuten lang behutsam mit Wasser spülen. Eventuell
vorhandene Kontaktlinsen nach Möglichkeit
entfernen. Weiter spülen.
P310 - Sofort GIFTINFORMATIONSZENTRUM, Arzt anrufen.
P333+P313 - Bei Hautreizung oder -ausschlag:
Ärztlichen Rat einholen/ärztliche Hilfe hinzuziehen.

Sicherheitsdatenblatt unter yellotools.com

UFI-Code: G2XR-Q0D4-4008-2PDV

Informationszentrale gegen Vergiftungen,
Zentrum für Kinderheilkunde,
Universitätsklinikum Bonn:
+49 (0) 228 19240

Gefahr



KONTAKT / CONTACT

Yellotools GmbH | Wilberhofer Str. 1 + 3 | 51570 Windeck Wilberhofen | Germany
Tel.: +49 (0) 22 92 - 397 40 - 0 | sales@yellotools.com | www.yellotools.com

Removes the nano coating on glass and varnish

Instructions for use

You will also need:

Polishing wool or a lint-free cloth, such
as our YelloFleecePro.

- **Preparation:**
Thoroughly clean the surface with
YelloJack and / or a standard cleaner.
- **Shake NanoEx well before use!**
- **Pour the cleaning milk onto the cloth or
polishing wool. Apply to the surface to
be treated in circular movements,
taking care not to press too hard.**
- **Please be sure to treat the entire
surface, such as glass panes, doors,
fenders, etc.!!**
- **Then rinse the surface with plenty of
water and allow to dry.**
- **Depending on the degree of coating,
repeat the process if necessary.**

Hazard statements

H315 - Causes skin irritation.
H317 - May cause an allergic skin reaction.
H318 - Causes serious eye damage.

Precautionary statements

P264 - Wash hands thoroughly after handling
P280 - Wear protective gloves, eye protection.
P305+P351+P338 - IF IN EYES: Rinse cautiously with water
for several minutes. Remove contact lenses, if
present and easy to do. Continue rinsing.
P310 - Immediately call a POISON CENTER, a doctor.
P333+P313 - If skin irritation or rash occurs:
Get medical advice/attention.

Danger

Safety Data Sheet can be found at yellotools.com

UFI-Code: G2XR-Q0D4-4008-2PDV

Informationszentrale gegen Vergiftungen,
Zentrum für Kinderheilkunde,
Universitätsklinikum Bonn: +49 (0) 228 19240

